



NASED Qualified Voting Systems  
as of 11/18/05

Company	Voting System/System Component	Software	Hardware/Firmware	System ID # / Qualified to '90 or '02 VSS	Final Report Date
<b>AutoMARK Technical Systems LLC</b>	ES&S AutoMARK Voting System Release 1.0	ES&S Unity v. 2.4.3 AutoMARK AIMS 1.09 (2002)	Model 100 Optical Scan Precinct Ballot Counter Firmware v. 5.0.0.0 Model 150/550 v. 2.1.1.0 Model 650 v. 1.2.0.0 Optech Eagle v. 1.50 APS, v. 1.28 HPS, CPS v. 1.02/C1.04 AutoMARK Voter Assist Terminal (VAT) v. 1.0 (2002)	N-1-16-22-12-001 (1990)	6/1/2005
<b>AutoMARK Technical Systems LLC</b>	ES&S AutoMARK Voting System	ES&S Unity v. 2.5 ES&S Unity v 3.0 AutoMARK AIMS 1.1.10	Model 100 Optical Scan Precinct Ballot Counter Firmware v. 5.1.0.0-Unity 2.5 Model 100 Optical Scan Precinct Ballot Counter Firmware v. 5.2.0.0-Unity 3.0 Model 650 Optical Scan Central Counter v. 2.0.1.0-Unity 2.5 Model 650 Optical Scan Central Counter v. 2.1.0.0-Unity 3.0 AutoMARK Voter Assist Terminal (VAT) v. 1.0.168	N-1-16-22-22-001 (2002)	10/24/2005



# NASD Qualified Voting Systems as of 11/18/05

<b>AccuPoll</b>	AccuPoll v. 2.3.14	MS Excel 9.0 MS Windows XP Pro 2002 s-pk.1 MS Windows 2000 Professional MS Internet Explorer 6.0 SP1 Red Hat Linux 7.2 AccuPoll EMS 2.3.14 AccuPoll In Precinct 2.3.14	Deil Dim 2350 Pentium IV PC Advantech Model PS-55AE PC APC UPS power supply Model 500 Lexmark Z55 Inkjet Printer Fastpoint FPV-215-L-8A Touchscreen CompactFlash 64mb Memory Card GemPlus GemPC430 VAW Smart Card Reader Uniform Industrial Corp. HCR330 AVS Smart Card Reader Audio Headphones Visually impaired keyboard (pending) Sony Model PCG-9E1L Laptop PC AccuPoll DRE AVS1 2.3.6 AccuPoll DRE AVS2 2.3.6 AccuPoll Visually impaired keyboard 2.3.6 Radio Shack Audio Headphones Standard CAT-5 Ethernet cables Sony Model PCG-9G1L Laptop PC NetGear Model FS108 Fast Ethernet switches Gateway X86 Pentium III Laptop PC	N-2-13-11-11-001 (1990)	2/20/2004
-----------------	--------------------	---	---	----------------------------	-----------



NASED Qualified Voting Systems  
as of 11/18/05

<p><b>AccuPoll</b></p>	<p>AccuPoll v. 2.5</p>	<p>MS XP Pro 2002 s-pk.1 Red Hat Linux 7.2 AccuPoll EMS 2.5 AccuPoll In Precinct 2.5 AccuPoll Ballot Builder 2.5</p>	<p>Dell Laptop PP01L HHP SR IT4600 scanner Lexmark Z705 Inkjet printer TFT LCD touchscreen overlay Standard Compact Flash UIC HCR331 AVS Smart Card Reader New Englan Keyboard (visually impaired keyboard) Enabling Devices (Sip&amp; Puff) Winbook 8640 Laptop Gemplus Smart Card Reader/Writer SpeedStream Fast Ethernet switches Sony PC, Keyboard KDS USA Monitor Hawking Technology 8 Port Ethernet switch Sony Vaio Laptop OKI Microline 490 printer Sony Laptop</p>	<p>N-2-13-22-22-001 (2002)</p>	<p>4/19/2005</p>
<p><b>Avante International</b></p>	<p>Optical Vote-Trakker 1.5.0</p>	<p>Optical Vote-Trakker 1.5.0 Count Ballots Rev. 1.00.4 V. 4.7.5 Ballot Preparation and Tally software</p>	<p>Canon DR5020 Scanner</p>	<p>N-1-12-22-22-002 (2002 )</p>	<p>5/12/2004</p>
<p><b>Avante International</b></p>	<p>Vote-Trakker EVC-308SPR Touch Screen DRE Firmware release 4.7.6</p>	<p>Manage Ballot date Rev. 3.8.1 Generate VID Rev. 4.0.5 Generate Ballot Data Rev. 5.1.1 Load Ballot Data Rev. Event 3.5.1 Log 4.0.0 Tally 4.0.2 (2002)</p>	<p>Dell Latitude D500 (14") Microsoft Windows 2000 Professional Version 5.0.2195/ServicePack 4 Build 2195 Dell Latitude C840 (15") Microsoft Windows 2000 Professional Version 5.0.2195/ServicePack 4 Build 2195 Seiko M/N KPU-s347-11H Printer USB Computer Keyboard used for Audio Vote Entry UPS Tripp-Lite M/N Internet 350</p>	<p>N-1-12-22-12-001 (1990)</p>	<p>5/20/2004</p>



NASED Qualified Voting Systems  
as of 11/18/05

<b>Danaher</b>	Guardian EMS 2.10 for ELECTronic 1242	Guardian EMS 2.10 / 2.10 DE (Delaware) Microsoft Windows 98 2nd ed. Microsoft Internet Explorer 6.0	ELECTronic 1242 DRE Firmware 4T10, 5T2 and 6T5. Danaher AED 6T Absentee entry device Pentium II 128MB RAM, 20 Gig Hard Drive PC Hewlett Packard HP2100 laser jet printer Hewlett Packard HP Design jet 1050 color plotter print	N04006000210 (1990) N04006000210-DE (1990)	12/5/2002
<b>Diebold</b>	GEMS 1-18-18	GEMS 1-18-18	AccuVote-OS Precinct Counter (formerly ES-2000) Firmware version 1.94W AccuVote-OS Precinct Counter Firmware version 1.96.4 AccuVote TS Precinct Counter Rev 6 version 1.0.2	N03060011818 (1990)	7/8/2003
<b>Diebold</b>	GEMS 1-18-19	GEMS 1-18-19	AccuVote-OS Precinct Counter Firmware version 1.94W AccuVote-OS Precinct Counter Firmware version 1.96.4	N-1-06-12-12-001 (1990)	2/3/2004



NASED Qualified Voting Systems  
as of 11/18/05

<b>Diebold</b>	GEMS 1-18-19	GEMS 1-18-19	AccuVote-OS Precinct Counter Firmware version 1.94W AccuVote-OS Precinct Counter Firmware version 1.96.4 AccuVote TS-R6 Precinct Counter Firmware Version 4.3.15D Windows CE OS 8/8/02 Bootloader 7/7/02 AccuVote TSx Precinct Counter Firmware Version 4.4.5 (2002) Spyrus Vote Card Encoder 1.3.2 (2002) Key Card Tool 1.0.1 (2002)	N-1-06-12-12-002 (1990)	5/20/2004
<b>Diebold</b>	GEMS 1-18-22	GEMS 1-18-22	AccuVote-OS Precinct Counter Firmware version 1.94W AccuVote-OS Precinct Counter Firmware version 1.96.4 AccuVote TS-R6 Precinct Counter Firmware Version 4.3.15D & 4.5.2 Windows CE OS 8/8/02 Bootloader 7/7/02 AccuVote TSx Precinct Counter Firmware Version 4.5.2 (2002) Vote Card Encoder 1.3.2 (2002) Key Card Tool 1.0.1 (2002)	N-1-06-12-12-003 (1990)	7/12/2004 9/29/2004
<b>Diebold</b>	GEMS 1-18-19	GEMS 1-18-19	AccuVote OS Central Count, Firmware version 2.0.12 (2002) VCPProgrammer 4.1.11 (2002)	N-1-06-12-12-004 (1990)	9/17/2004



NASED Qualified Voting Systems  
as of 11/18/05

<b>Diebold</b>	GEMS 1-18-22	GEMS 1-18-22	AccuVote OS Central Count, Firmware version 2.0.12 (2002) VCPProgrammer 4.1.11 (2002)	N-1-06-12-12-005 (1990)	9/17/2004
<b>Diebold</b>	GEMS 1-17-23	GEMS 1-17-23	AccuVote OS Central Count, Firmware version 2.0.12 VCPProgrammer 4.1.11	N-1-06-12-12-006 (1990)	9/17/2004
<b>Diebold</b>	GEMS 1-18-22G	GEMS 1-18-22G	AccuVote-TS Precinct Counter Rev 6 version 1.0.2 Windows CE3.0 Firmware version 4.5.2	N-1-06-12-12-007 (1990)	1/26/2005
<b>Diebold</b>	GEMS 1-18-22G	GEMS 1-18-22G	AccuVote TS Precinct Counter Rev 6 Version 1.0.2 Windows CE 3.0 Firmware Version 4.5.2 Express Poll 4000 1.1.5	N-1-06-12-12-009 (1990)	7/7/2005



NASED Qualified Voting Systems  
as of 11/18/05

<b>Diebold</b>	GEMS 1-18-22	GEMS 1-18-22	AccuVote TSx precinct count (touch screen) with AccuView Printer Module (AVPM) Bootloader BLR7-1.2.1 running WCER7-410.2.1 Firmware version 4.6.2 (2002)	N-1-06-12-22-008 (1990)	5/16/2005
<b>Diebold</b>	GEMS 1-18-24	GEMS 1-18-24	AccuVote-OS Precinct Count 1.96.6 Firmware AccuVote-OS Central Count 2.0.12 Firmware AccuVote TSx Precinct Counter with AVPM (Touch Screen with Printer Module) 4.6.3 Firmware Key card Tool 4.6.1 VCPProgrammer 4.6.1 Voter Card Encoder 1.3.2 Express Poll 4000 1.1.5	N-1-06-22-22-001 (2002)	6/27/2005
<b>Diebold</b>	GEMS 1-18-22 & GEMS 1-18-22G	GEMS 1-18-22 & GEMS 1-18-22G	AccuVote-TS Precinct Counter Rev 6 version 1.0.2 Windows CE3.0 Firmware version 4.5.2 AccuVote-TSx Precinct Counter Bootloader BLR7-1.2.1 running WCER7-410.2.1 Firmware version 4.6.4 AccuVote-TS Precinct Counter Rev 6 Version 1.0.2 running Windows CE 3.0 Firmware version 4.6.4 AccuVote-OS Precinct Count 1.96.6 Key Card Tool 4.6.1 Express Poll 2000	N-1-06-12-22-010 (1990)	9/21/2005



NASED Qualified Voting Systems  
as of 11/18/05

<p><b>Diebold</b></p>	<p>GEMS 1-18-24(A1)</p>	<p>GEMS 1-18-24(A1)</p>	<p>AccuVote-OS Precinct Count 1.96.6 Firmware AccuVote TSx Precinct Counter with AVPM (Touch Screen with Printer Module) and Accu-Vote TS R6 4.6.4 Firmware Key Card Tool 4.6.1 ABasic Report files 195US.abo Version 1.15</p>	<p>N-1-06-22-22-02 (2002)</p>	<p>10/3/2005</p>
<p><b>ES&amp;S</b></p>	<p>Unity 2.4.2</p>	<p>Election Data Manager v. 7.2.1.0, Audit Manager v.7.0.2.0, Optech Image Manager 3.2.0.0, ESS Image Manager v. 7.2.0.0, Ballot On Line v. 1.0.0.0, iVotronic Image Manager v. 1.2.3.0 Hardware, Programming Manager v. 5.0.2.0, Data Acquisition Manager v. 5.0.3.0, Election Reporting Manager v. 6.4.2.0</p>	<p>iVotronic DRE Firmware v. 8.0.0.0 Model 100 Optical Scan Precinct Ballot Counter Firmware v. 5.0.0.0 Model 150/550 v. 2.1.0.0 Model 650 v. 1.2.0.0 Votronic 5.19 and 5.30 Optech IV-C v. 1.06a and 1.07a* Eagle v. 1.50 APS, v. 1.28 HPS, CPS v. 1.02/C1.04</p>	<p>N-1-02-12-11-001 (1990)</p>	<p>2/19/2004</p>





NAS&S Qualified Voting Systems  
as of 11/18/05

<p><b>ES&amp;S</b></p>	<p>Unity 2.4.3</p>	<p>(changes from 2.4.2) Program Manager v. 5.0.3.0 Data Acquisition Manager v. 5.0.3.1 Election Reporting Manager v. 6.4.3.0</p>	<p>iVotronic DRE Firmware v. 8.0.1.0 Model 100 Optical Scan Precinct Ballot Counter Firmware v. 5.0.0.0 Model 150/550 v. 2.1.1.0 Model 650 v. 1.2.0.0 Votronic 5.19 and 5.30 Optech IV-C v. 1.06a and 1.07a* Eagle v. 1.50 APS, v. 1.28 HPS, CPS v. 1.02/C1.04</p>	<p>N-1-02-21-21-002 (1990)</p>	<p>8/27/2004</p>
<p><b>ES&amp;S</b></p>	<p>Unity 2.5</p>	<p>Audit Manager 7.3.0.0 Election Data Manager 7.3.0.0 ES&amp;S Image Manager 7.3.0.0 Hardware Programming Manager 5.1.0.0 Data Acquisition Manager 6.0.0.0 Election Reporting Manager 7.0.0.0 iVotronic Image Manager 2.0.1.0</p>	<p>iVotronic DRE Firmware v. 9.0.0.0 Model 650 Central Ballot Scanner Firmware release 2.0.1.0 Model 100 Precinct Ballot Counter Firmware release 5.1.0.0</p>	<p>N-1-02-22-22-003 (2002)</p>	<p>10/19/2004 11/11/2004 1/9/2005</p>
<p><b>ES&amp;S</b></p>	<p>Unity 3.0</p>	<p>Audit Manager 7.3.0.0 Election Data Manager 7.4.3.0 ES&amp;S Image Manager 7.4.1.0 Hardware Programming Manager 5.2.2.0 Data Acquisition Manager 6.0.0.0 Election Reporting Manager 7.1.1.0</p>	<p>iVotronic DRE with RTAL printer Firmware v. 9.1.2.0 ES&amp;S Communication Pack Model 650 Central Ballot Scanner Firmware release 2.1.0.0 Model 100 Precinct Ballot Counter Firmware release 5.2.0.0</p>	<p>N-2-02-22-22-004 (2002)</p>	<p>10/14/2005</p>



NASD Qualified Voting Systems  
as of 11/18/05

<p><b>ES&amp;S</b></p>	<p>Unity 2.4.3.1</p>				
<p><b>Hart</b></p>	<p>Hart InterCivic eSlate System Version 3.0</p>	<p>BOSS version 3.0.03.44, Ballot Now version 2.00.09, Rally version 1.1.13, Tally version 3.1.18.0, COTS software: MS Windows 2000 Professional, service Pack 4</p>	<p>Scanner = Kodak 1500D, Scanner = Fujitsu M4099D, Scanner = Fujitsu M4097D, Scanner = Kodak 3520D, Scanner = Kodak i840</p>	<p>N-1-04-12-12-001 (1990)</p>	<p>9/18/2003</p>
<p><b>Hart</b></p>	<p>Hart InterCivic eSlate System Version 3.1</p>	<p>BOSS version 3.4.0 Ballot Now version 2.1.0 Rally version 1.2.0 Tally version 3.2.0 Servo 2.0.10</p>	<p>Desktop workstation, Dell GX-1240, Ser. No. 956L111 Desktop workstation, Dell GX-1240, Ser. No. 746L111 JBC, Ser. No. C01026 Firmware Version 2.0.13 JBC, Ser. No. C01161 Firmware Version 2.0.13 eSlate3000 Ser. No. A04D10, Firmware Version 2.0.13 eSlate300</p>	<p>N-1-04-12-12-002 (1990)</p>	<p>12/19/2003</p>



**NASED Qualified Voting Systems  
as of 11/18/05**

<b>Hart</b>	Hart InterCivic eSlate System Version 3.2	BOSS version 3.4.0 Ballot Now version 2.02.05 & 2.02.06	Desktop workstation, Dell GX-240, Ser. No. 956L111 Desktop workstation, Dell GX-240, Ser. No. 746L111 MBB Card Reader Printer, HP DeskJet 932C, PSINET Number A000265656	N-1-04-12-12-003 (1990)	1/16/2004
<b>Hart</b>	Hart InterCivic eSlate System Version 3.3	BOSS version 3.4.0 Ballot Now version 2.3 Servo version 2.0.10 Rally version 1.2.0 Tally version 3.2.0	Desktop workstation, Dell GX-240, Ser. No. 956L111 Desktop workstation, Dell GX-240, Ser. No. 746L111 MBB Card Reader Printer, HP DeskJet 932C, PSINET Number A000265656	N-1-04-12-12-004 (1990)	5/5/2004
<b>Hart</b>	Hart InterCivic eSlate System Version 3.4	BOSS version 3.5.4 Ballot Now version 2.3 Servo version 2.0.10 Rally version 1.2.0 Tally version 3.2.0	eSlate 3000 release 2.3.8 JBC 1000 firmware revision 2.3.8	N-1-04-12-12-005 (1990)	8/2/2004



NASED Qualified Voting Systems  
as of 11/18/05

<p><b>Hart</b></p>	<p>Hart InterCivic eSlate System Version 4.0</p>	<p>BOSS version 4.0.48 Ballot Now version 3.0.24 Rally version 2.0.11 Tally version 4.0.25 eCM Manager 1.0.7 Servo 3.0.17 COTS software: MS Windows 2000 Prof, Service Pack 4</p>	<p>JBC Firmware Version 3.0.15 eSlate Firmware Version 3.0.15</p>	<p>N-1-04-22-22-001 (2002)</p>	<p>3/31/2005</p>
<p><b>Hart</b></p>	<p>Hart InterCivic eSlate System Version 4.1</p>	<p>BOSS version 4.0.48 Ballot Now version 3.0.24 Rally version 2.0.11 Tally version 4.0.25 eCM Manager 1.0.7 Servo 3.0.17 COTS software: MS Windows 2000 Prof, Service Pack 4</p>	<p>JBC Firmware Version 3.1.2 eSlate Firmware Version 3.1.2</p>	<p>N-1-04-22-22-002 (2002)</p>	<p>5/18/2005</p>
<p><b>Hart</b></p>	<p>Hart InterCivic eSlate System Version 5.0</p>	<p>BOSS version 4.1.9 Ballot Now version 3.1.10 Rally version 2.1.4 Tally version 4.1.4 eCM Manager 1.0.7 Servo 4.0.13 COTS software: MS Windows 2000 Prof, Service Pack 4 BOSS Util 2.3.8 HartLib 1.1.5</p>	<p>JBC Firmware Version 3.1.3 eSlate Firmware Version 3.1.3 eScan Firmware Version 1.0.10</p>	<p>N-1-04-22-22-003 (2002)</p>	<p>10/14/2005</p>



NASED Qualified Voting Systems  
as of 11/18/05

<b>Liberty Election Systems, LLC./NEDAP</b>	LibertyControl Election Management System Version 1.0	LibertyControl Version 1.0	LibertyVoteESU1 DRE	N-2-14-22-22-001 (2002)	11/9/2004
<b>Populex</b>	Digital Paper Ballot Voting System v. 1.0	Election Management System version 2.19	PopulexSlate version 8.09.01	N-2-15-22-22-001 (2002)	11/18/2004
<b>Populex</b>	Digital Paper Ballot Voting System v. 1.1	Election Management System version 2.19	PopulexSlate version 8.11.06	N-2-15-22-22-002 (2002)	5/23/2005
<b>Sequoia</b>	AVC Advantage DRE		AVC Advantage DRE Firmware version 7.00F	N010201 (1990)	3/28/1997
<b>Sequoia</b>	WinEDS version 2.6 Build 220	WinEDS ver. 2.6 (220)	AVC Edge DRE Touchscreen Firmware version 4.0	N03070026220 (1990)	7/25/2002



NASED Qualified Voting Systems  
as of 11/18/05

<b>Sequoia</b>	EMS/AERO version 3.54	EMS/AERO version 3.54	EMS/AERO version 3.54 Optech Ballot Wizard version 1.0 (2002) SPR Host version 1.04 MPR version 2.15	Insight Optical Ballot Reader ver. HPX.K/K1.38, APX.K2.04 Eagle Optical Ballot Reader ver. HPS.D/H1.30 Optech 4C Central Office Ballot Counter ver. WinETP 1.02B	N03070000354 (1990)	10/31/2002
<b>Sequoia</b>	EMS/AERO version 3.54.1	EMS/AERO version 3.54.1	Optech 3P Eagle APS.H1.52.980428.1040 CPS.H1.08A.980428.1150 HPS.D/H1.30.980428.1130 Optech Insight APX K2.06.021108.1600 CPX.J/K1.12.020412.1100 HPX.K/K1.40.021030.1110 Optech 400-C Ballot Counter WinETP 1.10.5 (2002)	Optech 3P Eagle APS.H1.52.980428.1040 CPS.H1.08A.980428.1150 HPS.D/H1.30.980428.1130 Optech Insight APX K2.06.021108.1600 CPX.J/K1.12.020412.1100 HPX.K/K1.40.021030.1110 Optech 400-C Ballot Counter WinETP 1.10.5 (2002)	N-1-07-12-12-001 (1990)	2/1/2005
<b>Sequoia</b>	WinEDS version 3.0	Workstation Client Software .99 Database Server Software .99 Report Server Software 1.02 (2002)	Workstation Client Software .99 Database Server Software Report Server Software 1.02 (2002)	Sequoia 400C Scanner/Tabulator, Firmware version 1.02b Sequoia Card Activator, Model 4.1 Sequoia Card Activator, Model 4.32 Sequoia Cartridge Reader/Writer AVC Edge DRE Touchscreen Model 3.1 Firmware version 4.1D	N-1-07-22-11-001 (1990)	8/18/2003
<b>Sequoia</b>	WinEDS version 3.0	Workstation Client Software .99 Database Server Software .99 Report Server Software 1.02 (2002)	Workstation Client Software .99 Database Server Software Report Server Software 1.02 (2002)	AVC Edge DRE Touchscreen Firmware version 4.1J/K	N-1-07-22-11-002 (1990)	9/25/2003 10/23/2003
<b>Sequoia</b>	WinEDS version 3.0	Workstation Client Software .99 Database Server Software .99 Report Server Software 1.02 (2002)	Workstation Client Software .99 Database Server Software Report Server Software 1.02 (2002)	AVC Edge DRE Touchscreen Firmware version 4.2	N-1-07-22-11-003 (1990)	10/9/2003



NASD Qualified Voting Systems  
as of 11/18/05

<p><b>Sequoia</b></p>	<p>WinEDS version 3.0.134</p>	<p>WinEDS version 3.0.134 (2002)</p>	<p>Optech 400C Scanner/Tabulator version 1.02b Sequoia AVC Edge, Model I version 4.2 Sequoia AVC Edge, Model II version 4.2 Sequoia AVC Advantage, firmware 8.00B Sequoia Card Activators, Rev. E version 4.32 Sequoia Cartridge Reader/Writer</p>	<p>N-1-07-22-11-004 (1990)</p>	<p>7/16/2004</p>
<p><b>Sequoia</b></p>	<p>WinEDS version 3.0.134</p>	<p>WinEDS version 3.0.134 (2002)</p>	<p>Sequoia (Optech) 400C Scanner/Tabulator, Firmware version 1.02b Sequoia AVC Edge Model II version 4.2a Sequoia AVC Edge Model I version 4.10 Sequoia AVC Edge Model I version 4.2a Sequoia AVC Advantage, version 9.00G Sequoia AVC Advantage, version 8.00B</p>	<p>N-1-07-22-11-005 (1990)</p>	<p>9/3/2004</p>
<p><b>Sequoia</b></p>	<p>WinEDS version 3.0.134</p>	<p>WinEDS version 3.0.134 (2002)</p>	<p>Sequoia (Optech) 400C Scanner/Tabulator, Firmware version 1.02b Sequoia AVC Edge Model II version 4.2a, &amp; 4.3.320 w. VeriVote Printer# Sequoia AVC Edge Model I version 4.10, 4.2a, &amp; 4.3.307 Sequoia AVC Advantage, version 9.00G Sequoia AVC Advantage, version 8.00B</p>	<p>N-1-07-22-11-006 (1990)</p>	<p>10/20/2004</p>



NASED Qualified Voting Systems  
as of 11/18/05

<b>Sequoia</b>	WinEDS version 3.0.134	WinEDS version 3.0.134 (2002)	Sequoia 400C /WinETP 1.10.5 Sequoia AVC Edge Model II version 4.3.320 w. VeriVote Printer# Sequoia AVC Edge Model I version 4.3.320	N-1-07-22-11-007 (1990)	5/19/2005
<b>TruVote</b>	TruVote Voter Validation and Verification System	TruVote 1.0.0 Microsoft Windows 2000 SP2 & SP3 Microsoft Internet Explorer 6.0 SP1 Epson TM-T8811 Partial Cut Print Driver	Inlight XIMFlex-B17686 PC Non touch Screen Inlight XIMFLEX-1B 768601-IT01 PC Touch Screen Puritron IT2000 PC Touch Screen Tripp-Lite Internet 350 Universal power supply WaspNest CCd Barcode Scanner Unitech MSR-206 Magnetic swipe card writer Unitech MS	N04005000100 (1990)	5/15/2003
<b>Unisyn Voting Solutions</b>	INKA Vote Precinct Ballot Counter Voting System Version 1.2	Ballot Generator 1.02 Election Converter 1.02 Election Loader 1.00 Vote Converter 1.00 Central Tabulation 1.02	Precinct Ballot Counter Firmware Version 1.9.2 ADA Audio Voting Unit (Rev. A) InkaVote Recorder Ser. No. 9999	N-1-17-22-22-001 (2002)	9/26/2005 11/16/2005





# NASED Qualified Voting Systems as of 11/18/05

<p>* The Optech systems tested and identified under this release are legacy systems/releases not independently qualified under ITA testing. Use of these units should be based on state and local testing.</p>	<p><b><i>Entries in italics denote systems or system components previously qualified but not included on prior NASED lists.</i></b></p>		<p># Edge Version 4.3.320 includes a configuration in which the serial number of the voting machine has been removed from all hardcopy output generated by the VeriVote printer in order to ensure the secrecy of the ballot in jurisdictions where more than one machine is used.</p>		